
August 2013	Purple Line – Supplemental Hazardous Materials Technical Report
	Annandia I. Dhatamark I an
	Appendix I – Photograph Log



Site 001 - Photo 01 - Office building



Site 001 - Photo 02 - 300-gallon diesel AST



Site 001 - Photo 03 - 300-gallon diesel AST label



Site 001 - Photo 04 - AST fill pipes

Appendix H - Photo Log
Page 1 of 409



Site 001 - Photo 05 - Emergency generator



Site 001 - Photo 06 - Fuel pumps



Site 001 - Photo 07 - 25-gallon diesel AST



Site 001 - Photo 08 - Pad-mounted transformer




Site 002 - Photo 01 - View of vacant lot



Site 003 - Photo 01 - Office building (American Society of Health)



Site 003 - Photo 02 - 250-gallon diesel AST



Site 003 - Photo 03 - 250-gallon diesel AST label

Appendix H - Photo Log
Page 3 of 409



Site 003 - Photo 04 - 50-gallon diesel daytank AST



Site 003 - Photo 05 - Emergency generator



Site 003 - Photo 06 - Paint storage



Site 003 - Photo 07 - Paint storage



Site 004 - Photo 01 - Public park



Site 004 - Photo 02 - Public park



Site 004 - Photo 03 - Pole-mounted transformer #1



Site 004 - Photo 04 - Pole-mounted transformer #2



Site 005 - Photo 01 - Office building



Site 005 - Photo 02 - 250-gallon diesel AST #1



Site 005 - Photo 03 - 250-gallon diesel AST #1



Site 005 - Photo 04 - 250-gallon diesel AST #2



Site 005 - Photo 05 - 250-gallon diesel AST #2



Site 005 - Photo 06 - Emergency generator



Site 005 - Photo 07 - Grease pits



Site 006 - Photo 01 - Office building (CMC Energy Services)

Appendix H - Photo Log
Page 7 of 409



Site 007 - Photo 01 - Residence



Site 008 - Photo 01 - Residence



Site 009 - Photo 01 - Residence



Site 010 - Photo 01 - Residence

Appendix H - Photo Log
Page 8 of 409



Site 011 - Photo 01 - Public park (Crescent Trail)



Site 012 - Photo 01 - Residence



Site 013 - Photo 01 - Residence



Site 014 - Photo 01 - Bank (PNC)



Site 015 - Photo 01 - Residence



Site 016 - Photo 01 - Residence



Site 016 - Photo 02 - Pole-mounted transformer



Site 017 - Photo 01 - Residence

Appendix H - Photo Log
Page 10 of 409



Site 018 - Photo 01 - Residence



Site 019 - Photo 01 - Athletic club



Site 019 - Photo 02 - Athletic club



Site 019 - Photo 03 - Pad-mounted transformer #1

Appendix H - Photo Log
Page 11 of 409



Site 019 - Photo 04 - Pad-mounted transformer #2



Site 019 - Photo 05 - Pole-mounted transformer



Site 019 - Photo 06 - Parking lot



Site 019 - Photo 07 - Parking lot

Appendix H - Photo Log
Page 12 of 409



Site 020 - Photo 01 - Residence



Site 021 - Photo 01 - Residence



Site 021 - Photo 02 - Residence



Site 022 - Photo 01 - Residence

Appendix H - Photo Log
Page 13 of 409



Site 023 - Photo 01 - Residence



Site 024 - Photo 01 - Residence



Site 025 - Photo 01 - Office (Maloney Contractors)



Site 026 - Photo 01 - Residence

Appendix H - Photo Log
Page 14 of 409



Site 027 - Photo 01 - Business front (Newtown Auto Body)



Site 027 - Photo 02 - Business entrance (Newtown Auto Body)



Site 027 - Photo 03 - Pole-mounted transformer



Site 027 - Photo 04 - Parking lot



Site 028 - Photo 01 - Residence



Site 028 - Photo 02 - Pole-mounted transformer



Site 029 - Photo 01 - Office building



Site 030 - Photo 01 - Residence

Appendix H - Photo Log
Page 16 of 409



Site 031 - Photo 01 - Office building



Site 032 - Photo 01 - Residence



Site 033 - Photo 01 - Residence



Site 034 - Photo 01 - Office building

Appendix H - Photo Log
Page 17 of 409



Site 035 - Photo 01 - Office building



Site 036 - Photo 01 - Office building



Site 037 - Photo 01 - Doctor's office and learning center



Site 038 - Photo 01 - Office building

Appendix H - Photo Log
Page 18 of 409



Site 039 - Photo 01 - Child care facility



Site 040 - Photo 01 - Office building



Site 041 - Photo 01 - Residence



Site 042 - Photo 01 - Office building

Appendix H - Photo Log Page 19 of 409



Site 042 - Photo 02 - Sign at office building



Site 042 - Photo 03 - Pad-mounted transformer



Site 042 - Photo 04 - Pole-mounted transformer



Site 043 - Photo 01 - Apartment building

Appendix H - Photo Log
Page 20 of 409



Site 044 - Photo 01 - Residence



Site 045 - Photo 01 - View of wooded lot



Site 046 - Photo 01 - Residence



Site 047 - Photo 01 - Residence and school


Appendix H - Photo Log
Page 21 of 409



Site 047 - Photo 02 - Pole-mounted transformer



Site 048 - Photo 01 - Residence



Site 049 - Photo 01 - Residence



Site 050 - Photo 01 - Residence

Appendix H - Photo Log
Page 22 of 409



Site 051 - Photo 01 - Residence



Site 052 - Photo 01 - Residence



Site 053 - Photo 01 - Residence



Site 054 - Photo 01 - Residence

Appendix H - Photo Log
Page 23 of 409



Site 055 - Photo 01 - Residence



Site 056 - Photo 01 - Residence



Site 056 - Photo 02 - Pole-mounted transformer



Site 057 - Photo 01 - Residence

Appendix H - Photo Log
Page 24 of 409



Site 057 - Photo 02 - Pole-mounted transformer



Site 058 - Photo 01 - Residence




Site 059 - Photo 01 - Residence



Site 060 - Photo 01 - Residence

Appendix H - Photo Log
Page 25 of 409







Site 062 - Photo 01 - Residence



Site 063 - Photo 01 - Residence



Site 064 - Photo 01 - Residence

Appendix H - Photo Log
Page 26 of 409



Site 065 - Photo 01 - Residence



Site 066 - Photo 01 - Residence



Site 067 - Photo 01 - Residence



Site 068 - Photo 01 - Residence

Appendix H - Photo Log
Page 27 of 409



Site 069 - Photo 01 - Residence



Site 070 - Photo 01 - Residence



Site 071 - Photo 01 - Residence



Site 072 - Photo 01 - Residence

Appendix H - Photo Log
Page 28 of 409



Site 072 - Photo 02 - Pole-mounted transformer



Site 073 - Photo 01 - Residence



Site 074 - Photo 01 - Residence



Site 075 - Photo 01 - Residence


Appendix H - Photo Log
Page 29 of 409



Site 076 - Photo 01 - Residence



Site 077 - Photo 01 - Residence



Site 078 - Photo 01 - Residence



Site 079 - Photo 01 - Residence

Appendix H - Photo Log
Page 30 of 409



Site 080 - Photo 01 - Residence



Site 081 - Photo 01 - Golf course



Site 081 - Photo 02 - Golf course



Site 081 - Photo 03 - Golf course

Appendix H - Photo Log
Page 31 of 409



Site 081 - Photo 04 - Golf course



Site 081 - Photo 05 - Golf course



Site 082 - Photo 01 - Dry cleaning facility (Parkway Cleaners)



Site 082 - Photo 02 - 55-gallon drums of dry cleaning chemicals

Appendix H - Photo Log
Page 32 of 409



Site 082 - Photo 03 - 55-gallon drums of waste dry cleaning chemicals



Site 082 - Photo 04 - Dry cleaning equipment



Site 082 - Photo 05 - Dry cleaning equipment



Site 083 - Photo 01 - Gas station (Sunoco)


Appendix H - Photo Log
Page 33 of 409



Site 083 - Photo 02 - UST tank field



Site 083 - Photo 03 - 240-gallon used oil AST



Site 083 - Photo 04 - 240-gallon used oil AST label



Site 083 - Photo 05 - Staining at used oil AST

Appendix H - Photo Log Page 34 of 409



Site 083 - Photo 06 - Used anti-freeze drums



Site 083 - Photo 07 - Used oil filters



Site 083 - Photo 08 - Oil and water separator



Site 083 - Photo 09 - Monitoring well

Appendix H - Photo Log
Page 35 of 409



Site 084 - Photo 01 - Gas station (Citgo)



Site 084 - Photo 02 - Used oil AST




Site 084 - Photo 03 - UST tank field



Site 085 - Photo 01 - Office building (Chevy Chase)

Appendix H - Photo Log
Page 36 of 409



Site 086 - Photo 01 - Business (T.W. Perry)



Site 086 - Photo 02 - Store front



Site 086 - Photo 03 - Diesel AST and heating oil AST



Site 086 - Photo 04 - Storage yard

Appendix H - Photo Log
Page 37 of 409



Site 087 - Photo 01 - Dry cleaning facility (Galaxie Cleaners)



Site 087 - Photo 02 - Business (Chevy Chase Lake shopping center)



Site 087 - Photo 03 - Sign at Chevy Chase Lake shopping center




Site 087 - Photo 04 - Upstairs entrance to shopping center

Appendix H - Photo Log
Page 38 of 409



Site 087 - Photo 05 - Chevy Chase Lake shopping center



Site 087 - Photo 06 - Chevy Chase Lake shopping center



Site 087 - Photo 07 - Loading dock area



Site 087 - Photo 08 - Pad-mounter transformer

Appendix H - Photo Log
Page 39 of 409



Site 087 - Photo 09 - Dumpster area



Site 087 - Photo 10 - Storage area



Site 088 - Photo 01 - Apartment buildings (Chevy Chase Lake)



Site 088 - Photo 02 - Apartment buildings (Chevy Chase Lake)

Appendix H - Photo Log
Page 40 of 409



Site 089 - Photo 01 - Apartment buildings (Chevy Chase Lake)



Site 089 - Photo 02 - Apartment building #1



Site 089 - Photo 03 - 3000-gallon heating oil UST #1



Site 089 - Photo 04 - Apartment building #2


Appendix H - Photo Log
Page 41 of 409



Site 089 - Photo 05 - 3000-gallon heating oil UST 2



Site 089 - Photo 06 - Apartment building #3



Site 089 - Photo 07 - 3000-gallon heating oil UST #3



Site 089 - Photo 08 - Apartment building #4

Appendix H - Photo Log
Page 42 of 409



Site 089 - Photo 09 - 3000-gallon heating oil UST #4



Site 089 - Photo 10 - Pad-mounted transformer



Site 090 - Photo 01 - Apartment building



Site 091 - Photo 01 - Entrance to gated community

Appendix H - Photo Log
Page 43 of 409



Site 092 - Photo 01 - Apartment buildings



Site 093 - Photo 01 - Townhouses



Site 094 - Photo 01 - Residence



Site 095 - Photo 01 - Residence

Appendix H - Photo Log
Page 44 of 409



Site 096 - Photo 01 - Residence



Site 097 - Photo 01 - Residence



Site 098 - Photo 01 - Residence



Site 099 - Photo 01 - Residence

Appendix H - Photo Log
Page 45 of 409



Site 100 - Photo 01 - Residence



Site 101 - Photo 01 - Residence



Site 102 - Photo 01 - Residence



Site 103 - Photo 01 - Residence

Appendix H - Photo Log
Page 46 of 409







Site 105 - Photo 01 - Residence



Site 106 - Photo 01 - Residence



Site 107 - Photo 01 - Residence

Appendix H - Photo Log
Page 47 of 409



Site 108 - Photo 01 - Residence



Site 109 - Photo 01 - Residence



Site 110 - Photo 01 - Residence



Site 110 - Photo 02 - Pole-mounted transformer

Appendix H - Photo Log
Page 48 of 409



Site 111 - Photo 01 - Wooded lot



Site 111 - Photo 02 - On-site well



Site 111 - Photo 03 - On-site well tag



Site 112 - Photo 01 - Residence


Appendix H - Photo Log
Page 49 of 409



Site 113 - Photo 01 - Residence



Site 114 - Photo 01 - Residence



Site 114 - Photo 02 - Pole-mounted transformer



Site 115 - Photo 01 - Rock Creek Park

Appendix H - Photo Log
Page 50 of 409



Site 115 - Photo 02 - Rock Creek Park



Site 116 - Photo 01 - Apartment buildings (Round Hill of Chevy Chase)



Site 116 - Photo 02 - Apartment buildings (Round Hill of Chevy Chase)



Site 116 - Photo 03 - Pole-mounted transformer at Building A

Appendix H - Photo Log
Page 51 of 409



Site 116 - Photo 04 - Building C



Site 116 - Photo 05 - Pole mounted transformer at Building C



Site 116 - Photo 06 - Vent at Building C



Site 116 - Photo 07 - Building D

Appendix H - Photo Log
Page 52 of 409



Site 116 - Photo 08 - Dumpster area



Site 117 - Photo 01 - New building



Site 117 - Photo 02 - Tank field at new building



Site 117 - Photo 03 - Tank field at new building

Appendix H - Photo Log
Page 53 of 409



Site 117 - Photo 04 - Fueling island and tank field



Site 117 - Photo 05 - New fueling island



Site 117 - Photo 06 - New fueling island



Site 117 - Photo 07 - Dumpsters and propane storage

Appendix H - Photo Log
Page 54 of 409



Site 117 - Photo 08 - Bus Parking at old building



Site 117 - Photo 09 - Parking at old building



Site 117 - Photo 10 - Service yard at old building



Site 117 - Photo 11 - Sign at old building

Appendix H - Photo Log
Page 55 of 409



Site 117 - Photo 12 - Tank signs and vent pipes at old building



Site 117 - Photo 13 - Tank field and repair bays at old building



Site 117 - Photo 14 - Old building



Site 117 - Photo 15 - Salt brine AST

Appendix H - Photo Log
Page 56 of 409



Site 117 - Photo 16 - Interior of salt barn



Site 117 - Photo 17 - Salt barn



Site 117 - Photo 18 - Salt barn and temporary barn



Site 117 - Photo 19 - Storage building

Appendix H - Photo Log
Page 57 of 409



Site 117 - Photo 20 - Sign on storage building



Site 118 - Photo 01 - Main building



Site 118 - Photo 02 - Entrance to Rock Creek Pool Club



Site 118 - Photo 03 - Pool area

Appendix H - Photo Log
Page 58 of 409



Site 118 - Photo 04 - Gas meter and power box at pump room



Site 118 - Photo 05 - Pump room



Site 118 - Photo 06 - Pool



Site 118 - Photo 07 - Interior of pump room at main building

Appendix H - Photo Log
Page 59 of 409



Site 118 - Photo 08 - Pump room at old building



Site 119 - Photo 01 - WSSC Lyttonsville service center building



Site 119 - Photo 02 - Sign at building



Site 119 - Photo 03 - UST tank field

Appendix H - Photo Log
Page 60 of 409



Site 119 - Photo 04 - UST tank field



Site 120 - Photo 01 - Entrance to county parking lot



Site 120 - Photo 02 - Leaf boxes



Site 120 - Photo 03 - Northern parking area

Appendix H - Photo Log
Page 61 of 409



Site 120 - Photo 04 - Pole-mounted transformer



Site 120 - Photo 05 - Southern parking area



Site 120 - Photo 06 - Parking lot



Site 121 - Photo 01 - Bus stop

Appendix H - Photo Log
Page 62 of 409



Site 121 - Photo 02 - Pole-mounted transformer



Site 121 - Photo 03 - WSSC undeveloped lot



Site 122 - Photo 01 - Vacant lot



Site 122 - Photo 02 - Vacant lot

Appendix H - Photo Log
Page 63 of 409



Site 123 - Photo 01 - Business (Former Carpentry & Millwork Casework)



Site 123 - Photo 02 - Storage and dumping area



Site 123 - Photo 03 - Dumping of construction debris



Site 124 - Photo 01 - Apartment building (Claridge House)

Appendix H - Photo Log
Page 64 of 409



Site 124 - Photo 02 - Sign at apartment building



Site 124 - Photo 03 - Entrance to apartment building



Site 124 - Photo 04 - 10,000-gallon heating oil UST in background and PEPCO vault in foreground



Site 124 - Photo 05 - 10,000-gallon heating oil UST on left and PEPCO vault on right

Appendix H - Photo Log
Page 65 of 409



Site 124 - Photo 06 - 10,000-gallon heating oil UST



Site 124 - Photo 07 - 10,000-gallon heating oil UST



Site 124 - Photo 08 - 10,000-gallon heating oil UST label



Site 124 - Photo 09 - HVAC system

Appendix H - Photo Log
Page 66 of 409



Site 124 - Photo 10 - HVAC system



Site 124 - Photo 11 - Dumpster



Site 124 - Photo 12 - PEPCO vault



Site 124 - Photo 13 - Pool area

Appendix H - Photo Log
Page 67 of 409



Site 124 - Photo 14 - Pool chemical storage



Site 124 - Photo 15 - Pool house



Site 124 - Photo 16 - Pool maintenance office



Site 124 - Photo 17 - Dumpster area

Appendix H - Photo Log
Page 68 of 409



Site 125 - Photo 01 - Entrance to site



Site 125 - Photo 02 - Entrance to site



Site 125 - Photo 03 - Entrance to site



Site 125 - Photo 04 - Former business (Auto Truck Sales)

Appendix H - Photo Log
Page 69 of 409



Site 125 - Photo 05 - Georgetown Branch Trail



Site 125 - Photo 06 - Landscape storage yard



Site 125 - Photo 07 - Landscape storage yard



Site 125 - Photo 08 - Landscape storage yard

Appendix H - Photo Log
Page 70 of 409



Site 125 - Photo 09 - Mulch recycling facility AST #1



Site 125 - Photo 10 - Mulch recycling facility AST #1



Site 125 - Photo 11 - Mulch recycling facility AST #1 label



Site 125 - Photo 12 - Mulch recycling facility

Appendix H - Photo Log
Page 71 of 409



Site 125 - Photo 13 - AST #2 and #3



Site 125 - Photo 14 - AST #2 and #3



Site 125 - Photo 15 - AST #2 and #3



Site 125 - Photo 16 - AST #2

Appendix H - Photo Log
Page 72 of 409



Site 125 - Photo 17 - AST #2 label



Site 125 - Photo 18 - AST #3 label



Site 125 - Photo 19 - Landscape storage yard with dumpster



Site 125 - Photo 20 - Landscape storage yard

Appendix H - Photo Log
Page 73 of 409





Site 125 - Photo 21 - AST #4

Site 125 - Photo 22 - AST #4







Site 125 - Photo 24 - AST #4

Appendix H - Photo Log
Page 74 of 409



Site 125 - Photo 25 - Entrance to storage yard



Site 125 - Photo 26 - Equipment storage area



Site 125 - Photo 27 - Former business (Campanaro Auto Sales)



Site 125 - Photo 28 - Pole-mounted transformer

Appendix H - Photo Log
Page 75 of 409



Site 125 - Photo 29 - Truck parking area



Site 126 - Photo 01 - Business (Noland Plumbing & Heating)



Site 126 - Photo 02 - Natural gas meter



Site 126 - Photo 03 - Former business (DaVincis Florist) with natural gas meter

Appendix H - Photo Log
Page 76 of 409



Site 126 - Photo 04 - Sign at business



Site 126 - Photo 05 - Pole-mounted transformer



Site 126 - Photo 06 - Dumpster



Site 127 - Photo 01 - Business (Richman Design)

Appendix H - Photo Log
Page 77 of 409



Site 128 - Photo 01 - Business (Brookville Eatery)



Site 128 - Photo 02 - Dumpsters



Site 128 - Photo 03 - Empty AST



Site 128 - Photo 04 - Pad-mounted transformer

Appendix H - Photo Log
Page 78 of 409



Site 128 - Photo 05 - Rear of site



Site 128 - Photo 06 - Rear of site



Site 128 - Photo 07 - Rear of site



Site 128 - Photo 08 - Southern end of site

Appendix H - Photo Log
Page 79 of 409



Site 128 - Photo 09 - Storage yard with dumpsters



Site 128 - Photo 10 - Rear of site along side street



Site 128 - Photo 11 - Business (Counter Intelligence Countertops)



Site 128 - Photo 12 - Business (Counter Intelligence Countertops)

Appendix H - Photo Log
Page 80 of 409



Site 128 - Photo 13 - Business (Counter Intelligence Countertops)



Site 128 - Photo 14 - Business (Frames by Rebecca)



Site 128 - Photo 15 - Pole-mounted transformer



Site 128 - Photo 16 - Natural gas meters

Appendix H - Photo Log
Page 81 of 409



Site 128 - Photo 17 - Business (Vaccaro's)



Site 128 - Photo 18 - Loading dock (Vaccaro's)



Site 128 - Photo 19 - Loading dock (Counter Intelligence Countertops)



Site 128 - Photo 20 - Dumpsters (Aireco)

Appendix H - Photo Log
Page 82 of 409



Site 128 - Photo 21 - Rear of property (Aireco)



Site 128 - Photo 22 - Business (Aireco)



Site 128 - Photo 23 - Restaurant (El Norteno)



Site 128 - Photo 24 - Georgetown Branch Trail

Appendix H - Photo Log
Page 83 of 409



Site 128 - Photo 25 - Business (Richman Design)



Site 128 - Photo 26 - Gas meter and dumpster



Site 128 - Photo 27 - Business (Richman Design)



Site 128 - Photo 28 - Rear of site (Ward & Gray)

Appendix H - Photo Log
Page 84 of 409



Site 128 - Photo 29 - Dumpster (Ward & Gray)



Site 129 - Photo 01 - Vacant lot



Site 129 - Photo 02 - Vacant lot



Site 130 - Photo 01 - Entrance to storage yard (Serra Stone)

Appendix H - Photo Log
Page 85 of 409



Site 130 - Photo 02 - AST



Site 130 - Photo 03 - Truck mounted ASTs



Site 130 - Photo 04 - Storage yard



Site 130 - Photo 05 - Storage yard and ASTs

Appendix H - Photo Log
Page 86 of 409



Site 130 - Photo 06 - Storage yard



Site 131 - Photo 01 - Street right of way



Site 132 - Photo 01 - Street right of way



Site 132 - Photo 02 - Street right of way

Appendix H - Photo Log
Page 87 of 409



Site 133 - Photo 01 - Building #1 (Brendan Mattingly Sitegraphy)



Site 133 - Photo 02 - Building #1 (Creative Concrete)



Site 133 - Photo 03 - Building #1 (Hansen Pool Service) with natural gas meter



Site 133 - Photo 04 - Building #1 (Levine Group)

Appendix H - Photo Log
Page 88 of 409



Site 133 - Photo 05 - Building #1 (Mitchell & Co) with natural gas meter



Site 133 - Photo 06 - Chemical shed at rear of Building #1



Site 133 - Photo 07 - Xylene drum in chemical shed at rear of Building #



Site 133 - Photo 08 - Chemical shed at rear of Building #1

Appendix H - Photo Log



Site 133 - Photo 09 - Dumping at rear of Building #1



Site 133 - Photo 10 - Storage yard at rear of Building #1



Site 133 - Photo 11 - Rear of Building #1



Site 133 - Photo 12 - Dumpster area at Building #2 (Encore Deco Storage)

Appendix H - Photo Log
Page 90 of 409



Site 133 - Photo 13 - Building #2 (Encore Deco Storage)



Site 133 - Photo 14 - Building #2 (Excellant Carpet Cleaning)



Site 133 - Photo 15 - Building #2 (Metro Scooters) with natural gas meter



Site 133 - Photo 16 - HVAC system at rear of Building #2

Appendix H - Photo Log
Page 91 of 409




Site 133 - Photo 17 - Rear of Building #2



Site 133 - Photo 18 - Dumpsters



Site 133 - Photo 19 - Entrance to parking lot



Site 134 - Photo 01 - Old service bay (Counter Intelligence Fabrication & Distribution)

Appendix H - Photo Log Page 92 of 409



Site 134 - Photo 02 - Parking area (Counter Intelligence Fabrication & Distribution)



Site 134 - Photo 03 - Rear of property



Site 134 - Photo 04 - Storage yard



Site 134 - Photo 05 - Storage yard

Appendix H - Photo Log
Page 93 of 409



Site 134 - Photo 06 - Storage yard



Site 134 - Photo 07 - Business (Counter Intelligence Fabrication & Distribution)



Site 134 - Photo 08 - Business (Counter Intelligence Fabrication & Distribution)



Site 134 - Photo 09 - Pole-mounted transformer

Appendix H - Photo Log
Page 94 of 409



Site 135 - Photo 01 - Auto repair facility (A Quality Auto)



Site 135 - Photo 02 - Used oil burner (A Quality Auto)



Site 135 - Photo 03 - Used oil burner (A Quality Auto)



Site 135 - Photo 04 - AST (Digregorio Drywall)

Appendix H - Photo Log
Page 95 of 409



Site 135 - Photo 05 - AST (Digregorio Drywall)



Site 135 - Photo 06 - AST (Digregorio Drywall)



Site 135 - Photo 07 - Dumpster (A Quality Auto)



Site 135 - Photo 08 - Business (Digregorio Drywall)

Appendix H - Photo Log



Site 135 - Photo 09 - Former railroad track



Site 135 - Photo 10 - Business (Frank's Scrap Metal)



Site 135 - Photo 11 - Parking lot



Site 135 - Photo 12 - Dumpster (WHAP)

Appendix H - Photo Log
Page 97 of 409



Site 135 - Photo 13 - Business (WHAP)



Site 136 - Photo 01 - Business (Amato Industries)



Site 136 - Photo 02 - Heating oil UST tankfield



Site 136 - Photo 03 - Heating oil tanker truck fueling area

Appendix H - Photo Log
Page 98 of 409



Site 136 - Photo 04 - Heating oil tanker truck fueling area



Site 136 - Photo 05 - Drycleaning fluid AST



Site 136 - Photo 06 - Chemical storage & UST



Site 136 - Photo 07 - Sodium hypochlorite ASTs & dispenser

Appendix H - Photo Log
Page 99 of 409



Site 136 - Photo 08 - Sodium hypochlorite ASTs



Site 136 - Photo 09 - Chemical Storage



Site 136 - Photo 10 - Chemical Storage



Site 136 - Photo 11 - Used oil AST

Appendix H - Photo Log



Site 136 - Photo 12 - Generator & heating oil AST



Site 136 - Photo 13 - Equipment storage area



Site 136 - Photo 14 - Storage yard



Site 136 - Photo 15 - Truck parking area

Appendix H - Photo Log Page 101 of 409



Site 136 - Photo 16 - Truck parking area



Site 137 - Photo 01 - Dumpster at Building #1 (ESP)



Site 137 - Photo 02 - Building #1 (ESP)



Site 137 - Photo 03 - Building #1 (ESP)

Appendix H - Photo Log



Site 137 - Photo 04 - Dumpsters at Building #1 (Flynn)



Site 137 - Photo 05 - Natural gas meters at Building #1 (Flynn)



Site 137 - Photo 06 - Building #1 (One of a Kind Art Studio)



Site 137 - Photo 07 - Building #1 (Planetary Systems Corp)

Appendix H - Photo Log
Page 103 of 409



Site 137 - Photo 08 - Building #1 (Planetary Systems Corp)



Site 137 - Photo 09 - Directory sign at Building #2



Site 137 - Photo 10 - Dumpsters at rear of Building #2



Site 137 - Photo 11 - Dumpsters at rear of Building #2

Appendix H - Photo Log
Page 104 of 409



Site 137 - Photo 12 - Storage at rear of Building #2



Site 137 - Photo 13 - Storage at rear of Building #2



Site 137 - Photo 14 - Storage at rear of Building #2



Site 137 - Photo 15 - Truck parking at Building #2

Appendix H - Photo Log Page 105 of 409



Site 137 - Photo 16 - Building #2



Site 137 - Photo 17 - Building #3 (Four Feet to the Yard)



Site 137 - Photo 18 - Natural gas meter at Building #3 (InterPark Maintenance Deptartment)




Site 137 - Photo 19 - Pole-mounted transformer (Building #3)

Appendix H - Photo Log Page 106 of 409



Site 137 - Photo 20 - Landscape material storage at area of Building #3



Site 137 - Photo 21 - Sign at Building #3



Site 137 - Photo 22 - Dumpsters at Building #3 (Solar City)



Site 137 - Photo 23 - Storage yard at Building #3 (Solar City)

Appendix H - Photo Log
Page 107 of 409



Site 138 - Photo 01 - Railroad right of way



Site 138 - Photo 02 - Unused railroad track



Site 138 - Photo 03 - Empty drums (Amato Industries)



Site 139 - Photo 01 - Residence

Appendix H - Photo Log Page 108 of 409



Site 139 - Photo 02 - Residence



Site 140 - Photo 01 - Residence



Site 141 - Photo 01 - Residence



Site 142 - Photo 01 - Residence with natural gas meter

Appendix H - Photo Log



Site 143 - Photo 01 - Residence



Site 143 - Photo 02 - Residence



Site 144 - Photo 01 - Residence



Site 145 - Photo 01 - View of metro easement

Appendix H - Photo Log



Site 145 - Photo 02 - View of metro easement



Site 145 - Photo 03 - View of metro easement



Site 146 - Photo 01 - Rosemary Hills Elementary School



Site 146 - Photo 02 - Rosemary Hills Elementary School

Appendix H - Photo Log Page 111 of 409



Site 146 - Photo 03 - Pad-mounted transformer at rear of site



Site 146 - Photo 04 - Pad-mounted transformer



Site 146 - Photo 05 - Natural gas boilers



Site 146 - Photo 06 - Dumpsters and HVAC equipment

Appendix H - Photo Log Page 112 of 409



Site 147 - Photo 01 - Residence with natural gas meter



Site 148 - Photo 01 - Residence



Site 149 - Photo 01 - Residence with natural gas meter



Site 150 - Photo 01 - Entrance to townhouse community (Woodside Mews)

Appendix H - Photo Log Page 113 of 409



Site 150 - Photo 02 - Pad-mounted transformers #1



Site 150 - Photo 03 - Leakage at base of pad-mounted transformers #1



Site 150 - Photo 04 - Leakage at base of pad-mounted transformers #1



Site 150 - Photo 05 - Pad-mounted transformer #2

Appendix H - Photo Log
Page 114 of 409



Site 150 - Photo 06 - Pad-mounted transformer #2



Site 150 - Photo 07 - Pad-mounted transformer #2



Site 150 - Photo 08 - Residence with fire damage



Site 150 - Photo 09 - Residence with fire damage

Appendix H - Photo Log
Page 115 of 409



Site 150 - Photo 10 - Residence with fire damage



Site 150 - Photo 11 - Residence with fire damage



Site 150 - Photo 12 - Residence with fire damage



Site 150 - Photo 13 - Residence with fire damage

Appendix H - Photo Log Page 116 of 409



Site 151 - Photo 01 - Right of way



Site 151 - Photo 02 - Right of way



Site 151 - Photo 03 - Dumping along right of way



Site 151 - Photo 04 - Dumping along railroad

Appendix H - Photo Log Page 117 of 409



Site 151 - Photo 05 - Switch box along railroad tracks



Site 151 - Photo 06 - Railroad switch box with staining



Site 151 - Photo 07 - Railroad switch box



Site 151 - Photo 08 - Railroad switch box label

Appendix H - Photo Log
Page 118 of 409



Site 151 - Photo 09 - Pole-mounted transformer



Site 151 - Photo 10 - Railroad structures



Site 151 - Photo 11 - Railroad control room and switch boxes



Site 151 - Photo 12 - Railroad switch box

Appendix H - Photo Log
Page 119 of 409



Site 151 - Photo 13 - Railroad switch boxes



Site 151 - Photo 14 - Right of way adjacent to apartment buildings



Site 152 - Photo 01 - Apartment buildings



Site 152 - Photo 02 - Pole-mounted transformer

Appendix H - Photo Log Page 120 of 409



Site 152 - Photo 03 - Pole-mounted transformer



Site 152 - Photo 04 - Boiler room



Site 152 - Photo 05 - Pole-mounted transformer near leasing center



Site 152 - Photo 06 - Pool chemical storage building

Appendix H - Photo Log
Page 121 of 409



Site 152 - Photo 07 - Pool



Site 152 - Photo 08 - Dumpster and pole-mounted transformer



Site 152 - Photo 09 - Dumpster area near tennis courts



Site 152 - Photo 10 - Dumpster area

Appendix H - Photo Log



Site 152 - Photo 11 - Leasing and community center



Site 152 - Photo 11 - Natural gas meter at community center



Site 153 - Photo 01 - Apartment building (8600 Luxury Rentals)



Site 153 - Photo 02 - UST

Appendix H - Photo Log Page 123 of 409



Site 153 - Photo 03 - UST

Site 153 - Photo 04 - UST



Site 153 - Photo 05 - UST label



Site 153 - Photo 06 - Dumping of drums

Appendix H - Photo Log
Page 124 of 409



Site 153 - Photo 07 - Dumping of drums



Site 153 - Photo 08 - Pool chemical storage building



Site 153 - Photo 09 - Pool chemical storage sign



Site 153 - Photo 10 - Pool

Appendix H - Photo Log
Page 125 of 409



Site 153 - Photo 11 - PEPCO Vaults



Site 153 - Photo 12 - Boiler room



Site 153 - Photo 13 - Dumpsters



Site 154 - Photo 01 - Railroad easement

Appendix H - Photo Log
Page 126 of 409



Site 155 - Photo 01 - Railroad easement



Site 155 - Photo 02 - Electrical building



Site 155 - Photo 03 - Vacant lot



Site 156 - Photo 01 - Railroad easement

Appendix H - Photo Log
Page 127 of 409



Site 157 - Photo 01 - Multiple businesses at Building #1



Site 157 - Photo 02 - Multiple businesses at Building #1



Site 157 - Photo 03 - Multiple businesses at Building #1



Site 157 - Photo 04 - Multiple businesses at Building #1

Appendix H - Photo Log Page 128 of 409



Site 157 - Photo 05 - Grease spill at rear of building #1



Site 157 - Photo 06 - Grease spill at rear of building #1



Site 157 - Photo 07 - Natural gas meters at rear of building #1



Site 157 - Photo 08 - Natural gas meters at rear of building #1

Appendix H - Photo Log Page 129 of 409



Site 157 - Photo 09 - Multiple businesses at building #2



Site 157 - Photo 10 - Multiple businesses at building #2



Site 157 - Photo 11 - Multiple businesses at building #2



Site 157 - Photo 12 - Multiple businesses at building #2

Appendix H - Photo Log Page 130 of 409



Site 157 - Photo 13 - Multiple businesses at building #2



Site 157 - Photo 14 - Dry cleaning facility at building #2



Site 157 - Photo 15 - Dry cleaning facility at building #2



Site 157 - Photo 16 - Pad-mounted transformer at building #2

Appendix H - Photo Log
Page 131 of 409



Site 157 - Photo 17 - Pad-mounted transformer at building #2



Site 157 - Photo 18 - Dumpster area at rear of building #2



Site 157 - Photo 19 - Dumpster area at rear of building #2



Site 157 - Photo 20 - Dumpster area at rear of building #2

Appendix H - Photo Log
Page 132 of 409



Site 157 - Photo 21 - Dumpster area at rear of building #2



Site 157 - Photo 22 - Building 2 Rear Natural gas meters



Site 157 - Photo 23 - Building 2 Rear Storefronts



Site 157 - Photo 24 - Spring Center Road Frontage

Appendix H - Photo Log Page 133 of 409



Site 157 - Photo 25 - Dumpster area at building #2



Site 158 - Photo 01 - Railroad easement



Site 158 - Photo 02 - Railroad easement



Site 159 - Photo 01 - Business (Blockbuster)

Appendix H - Photo Log
Page 134 of 409



Site 159 - Photo 02 - Dumpsters



Site 159 - Photo 03 - Natural gas meter



Site 160 - Photo 01 - Office building



Site 161 - Photo 01 - Railroad easement

Appendix H - Photo Log
Page 135 of 409



Site 162 - Photo 01 - U.S. Post Office



Site 162 - Photo 02 - Pad-mounted transformer



Site 162 - Photo 03 - Generator storage



Site 162 - Photo 04 - Generator

Appendix H - Photo Log
Page 136 of 409



Site 162 - Photo 05 - Spill Kit



Site 163 - Photo 01 - Office buildings



Site 163 - Photo 02 - Pole-mounted transformer



Site 163 - Photo 03 - Pole-mounted transformer

Appendix H - Photo Log
Page 137 of 409



Site 163 - Photo 04 - Dumpster area



Site 163 - Photo 05 - Unknown manhole



Site 164 - Photo 01 - Railroad easement



Site 165 - Photo 01 - Apartment buildings

Appendix H - Photo Log
Page 138 of 409



Site 165 - Photo 02 - Pad-mounted transformer #1



Site 165 - Photo 03 - Pad-mounted transformer #2



Site 165 - Photo 04 - Pad-mounted transformer #3



Site 165 - Photo 05 - Pole-mounted transformer

Appendix H - Photo Log
Page 139 of 409



Site 166 - Photo 01 - Business (Rite Aid)



Site 167 - Photo 01 - Business (Fed Ex)



Site 168 - Photo 01 - Area behind Site 142 Building #1



Site 168 - Photo 02 - Area behind Site 142 Building #2

Appendix H - Photo Log
Page 140 of 409



Site 169 - Photo 01 - Metro substation



Site 169 - Photo 02 - Metro substation



Site 170 - Photo 01 - Railroad easement



Site 170 - Photo 02 - Railroad easement

Appendix H - Photo Log Page 141 of 409



Site 171 - Photo 01 - Railroad easement



Site 171 - Photo 02 - Railroad easement



Site 172 - Photo 01 - Office building



Site 172 - Photo 02 - Generator and 225-gallon diesel AST


Appendix H - Photo Log
Page 142 of 409




Site 172 - Photo 03 - Generator and 225-gallon diesel AST



Site 172 - Photo 04 - Emergency generator and AST



Site 172 - Photo 05 - Emergency generator and AST



Site 172 - Photo 06 - #2 Fuel Oil AST

Appendix H - Photo Log
Page 143 of 409



Site 172 - Photo 07 - AST vent pipes



Site 172 - Photo 08 - AST vent pipes



Site 176 - Photo 01 - Parking garage construction site



Site 176 - Photo 02 - Parking garage construction site

Appendix H - Photo Log Page 144 of 409



Site 176 - Photo 03 - Parking garage construction site



Site 176 - Photo 04 - Parking garage construction site



Site 176 - Photo 05 - Parking garage construction site



Site 176 - Photo 06 - Parking garage construction site

Appendix H - Photo Log Page 145 of 409




Site 178 - Photo 01 - Office building



Site 179 - Photo 01 - Parking garage



Site 179 - Photo 02 - Multiple pad-mounted transformers



Site 180 - Photo 01 - Parking garage

Appendix H - Photo Log Page 146 of 409




Site 180 - Photo 02 - Oil and water separator



Site 181 - Photo 01 - Office building



Site 181 - Photo 02 - Diesel AST



Site 181 - Photo 03 - Diesel AST label


Appendix H - Photo Log
Page 147 of 409



Site 181 - Photo 04 - AST fill pipe



Site 182 - Photo 01 - Restaurant



Site 183 - Photo 01 - Office building



Site 184 - Photo 01 - Bank (Capitol One)



Site 185 - Photo 01 - Restaurant



Site 186 - Photo 01 - Dry cleaning facility



Site 187 - Photo 01 - Multiple businesses



Site 188 - Photo 01 - Auto repair facility (Tacoma Old Town)

Appendix H - Photo Log Page 149 of 409



Site 188 - Photo 02 - 500-gallon UST




Site 188 - Photo 03 - 55-gallons drums of virgin oil



Site 188 - Photo 04 - 55-gallons drums of antifreeze



Site 189 - Photo 01 - Office Building



Site 190 - Photo 01 - Office building



Site 190 - Photo 02 - 225-gallon fuel oil AST



Site 190 - Photo 03 - 225-gallon fuel oil AST



Site 190 - Photo 04 - Heating oil UST fill pipe and vent

Appendix H - Photo Log Page 151 of 409



Site 190 - Photo 05 - Natural gas shutoff valve



Site 191 - Photo 01 - Office building



Site 192 - Photo 01 - Office building



Site 192 - Photo 02 - Office building

Appendix H - Photo Log Page 152 of 409



Site 192 - Photo 03 - 225-gallon fuel oil AST



Site 192 - Photo 04 - 225-gallon fuel oil AST



Site 192 - Photo 05 - Oil fill and vent pipe



Site 193 - Photo 01 - Restaurant

Appendix H - Photo Log
Page 153 of 409



Site 194 - Photo 01 - Multiple businesses



Site 194 - Photo 02 - Pole-mounted transformer



Site 195 - Photo 01 - Parking lot



Site 195 - Photo 02 - Staining at base of pole-mounted transformer

Appendix H - Photo Log Page 154 of 409



Site 196 - Photo 01 - Business (Health Food Store)



Site 197 - Photo 01 - Condo building



Site 197 - Photo 02 - Pad-mounted transformer



Site 198 - Photo 01 - Gas station (Citgo)



Site 198 - Photo 02 - UST tank field



Site 198 - Photo 03 - 550-gallon used oil UST



Site 198 - Photo 04 - 55-gallon drums of antifreeze



Site 199 - Photo 01 - Construction site


Appendix H - Photo Log
Page 156 of 409



Site 199 - Photo 02 - Construction site



Site 200 - Photo 01 - Parking garage




Site 201 - Photo 01 - Office building



Site 201 - Photo 02 - Diesel generator



Site 201 - Photo 03 - Diesel generator



Site 201 - Photo 04 - Diesel generator label



Site 201 - Photo 05 - Oil and water separator



Site 202 - Photo 01 - Shopping center

Appendix H - Photo Log
Page 158 of 409



Site 202 - Photo 02 - Pad-mounted transformer



Site 202 - Photo 03 - Oil and water separator #1




Site 202 - Photo 04 - Oil and water separator #2



Site 203 - Photo 01 - Church







Site 204 - Photo 01 - School



Site 205 - Photo 01 - Residence



Site 205 - Photo 02 - Pole-mounted transformer



Site 206 - Photo 01 - Residence



Site 206 - Photo 02 - Pole-mounted transformer



Site 207 - Photo 01 - Residence



Site 207 - Photo 02 - Natural gas shutoff valve

Appendix H - Photo Log
Page 161 of 409



Site 208 - Photo 01 - Residence



Site 209 - Photo 01 - St. Michaels Church



Site 209 - Photo 02 - Pad-mounted transformer



Site 209 - Photo 03 - Pad-mounted transformer



Site 209 - Photo 04 - HVAC system



Site 210 - Photo 01 - Office building



Site 210 - Photo 02 - Pad-mounted transformer



Site 211 - Photo 01 - Residence

Appendix H - Photo Log
Page 163 of 409



Site 212 - Photo 01 - Residence



Site 212 - Photo 02 - Residence



Site 213 - Photo 01 - Residence



Site 214 - Photo 01 - Residence and doctor's office



Site 215 - Photo 01 - Residence



Site 216 - Photo 01 - Residence



Site 217 - Photo 01 - Residence



Site 218 - Photo 01 - Residence

Appendix H - Photo Log
Page 165 of 409



Site 219 - Photo 01 - Residence



Site 220 - Photo 01 - Residence



Site 221 - Photo 01 - Residence



Site 222 - Photo 01 - Residence

Appendix H - Photo Log
Page 166 of 409



Site 222 - Photo 02 - Pole-mounted transformer



Site 223 - Photo 01 - Residence




Site 224 - Photo 01 - Residence



Site 225 - Photo 01 - Residence

Appendix H - Photo Log
Page 167 of 409







Site 227 - Photo 01 - Residence



Site 228 - Photo 01 - Residence



Site 229 - Photo 01 - Residence

Appendix H - Photo Log
Page 168 of 409



Site 230 - Photo 01 - Residence



Site 231 - Photo 01 - Apartment buildings (Senior Living Center)



Site 231 - Photo 02 - Natural gas emergency generator



Site 231 - Photo 03 - Natural gas emergency generator supply lines

Appendix H - Photo Log Page 169 of 409



Site 232 - Photo 01 - Residence



Site 233 - Photo 01 - Residence



Site 234 - Photo 01 - Residence



Site 234 - Photo 02 - Pole-mounted transformer



Site 235 - Photo 01 - Residence



Site 236 - Photo 01 - Residence



Site 237 - Photo 01 - Residence



Site 238 - Photo 01 - Residence

Appendix H - Photo Log
Page 171 of 409



Site 239 - Photo 01 - Residence



Site 240 - Photo 01 - Residence



Site 241 - Photo 01 - Residence



Site 242 - Photo 01 - Residence

Appendix H - Photo Log
Page 172 of 409







Site 244 - Photo 01 - Residence



Site 245 - Photo 01 - Residence



Site 246 - Photo 01 - Residence

Appendix H - Photo Log
Page 173 of 409



Site 246 - Photo 02 - Pole-mounted transformer



Site 247 - Photo 01 - Residence



Site 248 - Photo 01 - Residence



Site 249 - Photo 01 - Residence




Site 250 - Photo 01 - Silver Spring International Middle School



Site 250 - Photo 02 - Silver Spring International Middle School



Site 250 - Photo 03 - 3000-gallon UST



Site 250 - Photo 04 - 3000-gallon UST vent

Appendix H - Photo Log
Page 175 of 409



Site 250 - Photo 06 - 3000-gallon UST sign



Site 250 - Photo 07 - Pad-mounted transformer



Site 250 - Photo 08 - Pole-mounted transformer #1



Site 250 - Photo 09 - Pole-mounted transformer #2

Appendix H - Photo Log
Page 176 of 409



Site 250 - Photo 10 - Pole-mounted transformer #3



Site 250 - Photo 11 - Pole-mounted transformer #4



Site 250 - Photo 12 - Pole-mounted transformer #5



Site 250 - Photo 13 - Pole-mounted transformer #6



Site 250 - Photo 14 - 1,000-pound propane AST



Site 251 - Photo 01 - Residence



Site 252 - Photo 01 - Residence



Site 253 - Photo 01 - Residence



Site 254 - Photo 01 - Residence



Site 254 - Photo 02 - Grass lot



Site 255 - Photo 01 - Residence



Site 256 - Photo 01 - Residence



Site 257 - Photo 01 - Residence



Site 258 - Photo 01 - Residence



Site 259 - Photo 01 - Residence



Site 260 - Photo 01 - Residence



Site 261 - Photo 01 - Residence



Site 262 - Photo 01 - Residence



Site 263 - Photo 01 - Residence



Site 264 - Photo 01 - Residence

Appendix H - Photo Log
Page 181 of 409







Site 266 - Photo 01 - Residence



Site 267 - Photo 01 - Residence



Site 268 - Photo 01 - Residence

Appendix H - Photo Log
Page 182 of 409



Site 269 - Photo 01 - Residence



Site 270 - Photo 01 - Residence



Site 271 - Photo 01 - Residence



Site 272 - Photo 01 - Wooded lot

Appendix H - Photo Log
Page 183 of 409



Site 273 - Photo 01 - Park



Site 273 - Photo 02 - Athletic fields at Silver Spring International Middle School



Site 274 - Photo 01 - Sligo Creek and wooded lot



Site 275 - Photo 01 - Wooded lot



Site 276 - Photo 01 - Apartment buildings



Site 276 - Photo 02 - Natural gas meter



Site 277 - Photo 01 - Residence



Site 278 - Photo 01 - Apartment buildings (Sligo Terrace Apartments)

Appendix H - Photo Log
Page 185 of 409



Site 278 - Photo 02 - Possible heating oil UST



Site 278 - Photo 03 - Possible heating oil UST fill pipe



Site 278 - Photo 04 - Possible heating oil UST piping sump



Site 278 - Photo 05 - Pole-mounted transfomer

Appendix H - Photo Log
Page 186 of 409



Site 278 - Photo 06 - Old coal burner



Site 278 - Photo 07 - Natural gas meter



Site 279 - Photo 01 - Wayne Avenue



Site 280 - Photo 01 - Apartment buildings (Wayne Manchester Towers)



Site 280 - Photo 02 - 5,000-gallon heating oil UST



Site 280 - Photo 03 - 5,000-gallon heating oil UST vent pipe



Site 281 - Photo 01 - Apartment buildings (Park Wayne Apartments)



Site 281 - Photo 02 - Pad-mounted transformer

Appendix H - Photo Log Page 188 of 409



Site 281 - Photo 03 - Pole-mounted transformer



Site 282 - Photo 01 - Condo building (Kenwood House)



Site 282 - Photo 02 - Pole-mounted transformer



Site 283 - Photo 01 - Residence and apartments

Appendix H - Photo Log
Page 189 of 409



Site 284 - Photo 01 - Residence and apartments



Site 285 - Photo 01 - Residence



Site 286 - Photo 01 - Residence



Site 286 - Photo 02 - Pole-mounted transformer







Site 288 - Photo 01 - Apartments




Site 289 - Photo 01 - Wayne Avenue



Site 290 - Photo 01 - Residence

Appendix H - Photo Log
Page 191 of 409







Site 292 - Photo 01 - Residence



Site 293 - Photo 01 - Residence



Site 294 - Photo 01 - Residence

Appendix H - Photo Log
Page 192 of 409



Site 295 - Photo 01 - Residence



Site 296 - Photo 01 - Residence



Site 297 - Photo 01 - Residence



Site 298 - Photo 01 - Townhome community


Appendix H - Photo Log
Page 193 of 409



Site 305 - Photo 01 - Parking



Site 306 - Photo 01- Townhome community



Site 313 - Photo 01 - Residence



Site 313 - Photo 02 - Restaurant

Appendix H - Photo Log
Page 194 of 409



Site 313 - Photo 03 - Parking lot



Site 313 - Photo 04 - Parking lot



Site 314 - Photo 01 - Business (Giant grocery store)



Site 314 - Photo 02 - Emergency generator and 500-gallon AST

Appendix H - Photo Log Page 195 of 409



Site 314 - Photo 03 - Emergency generator



Site 314 - Photo 04 - Pad-mounted transformer



Site 314 - Photo 05 - Pole-mounted transformer



Site 314 - Photo 06 - Location of removed UST



Site 314 - Photo 07 - Oil and water separator



Site 314 - Photo 08 - Natural gas meter



Site 315 - Photo 01 - Public library (Long Branch Public Library)



Site 315 - Photo 02 - Pad-mounted transformer



Site 316 - Photo 01 - Apartment buildings (Flower Branch Apartments)



Site 316 - Photo 02 - Pole mounted transformer #1



Site 316 - Photo 03 - Pole mounted transformer #2



Site 316 - Photo 04 - Pole mounted transformer #3

Appendix H - Photo Log
Page 198 of 409



Site 316 - Photo 05 - Pole mounted transformer #4



Site 316 - Photo 06 - Pole mounted transformer #5



Site 316 - Photo 07 - Pole mounted transformer #6



Site 316 - Photo 08 - Pole mounted transformer #7

Appendix H - Photo Log
Page 199 of 409



Site 316 - Photo 09 - Pole-mounted transformer #8



Site 316 - Photo 10 - Pole-mounted transformer #9



Site 317 - Photo 01 - Gas station (Washington Express)



Site 317 - Photo 02 - UST tank field



Site 317 - Photo 03 - Abandoned monitoring well #1



Site 317 - Photo 04 - Abandoned monitoring well #2



Site 318 - Photo 01 - Gas station (Shell)



Site 318 - Photo 02 - UST tank field

Appendix H - Photo Log
Page 201 of 409



Site 318 - Photo 03 - Used oil AST



Site 318 - Photo 04 - Oil and water separator



Site 318 - Photo 05 - Abandoned monitoring well



Site 319 - Photo 01 - Auto repair facility (Collision and Repair Shop)



Site 319 - Photo 02 - Auto repair facility (Collision and Repair Shop)



Site 319 - Photo 03 - Used oil AST (Collision and Repair Shop)



Site 319 - Photo 04 - Shopping center



Site 319 - Photo 05 - Sign at shopping center

Appendix H - Photo Log Page 203 of 409



Site 320 - Photo 01 - Apartment buildings (Gold Acres Apartments)



Site 320 - Photo 02 - 10,000-gallon heating oil UST (Gold Acres Apartments)



Site 320 - Photo 03 - 10,000-gallon heating oil UST manhole (Gold Acres Apartments)



Site 320 - Photo 04 - 10,000-gallon heating oil UST monitoring pipe (Gold Acres Apartments)

Appendix H - Photo Log
Page 204 of 409